

This airstrip is not shown on air navigation maps or listed in any publications. It now has few obstacles or hazards, but use is at pilots risk. Check aircraft insurance for use of uncharted and nonpublished airstrips.

Obstacles:

*50 ft tall power poles that run 145 ft parallel to the right side (East) of approach to Rwy 36.

*Diagonal tree line on the East side of the South end of the runway can cause erratic air movement with southeast wind.

*Beware of vehicles, farm machinery, domestic & wild animals, and other possible obstacles on runway.

Makato VOR 109.8
189 degrees 31.8 DME

Salina VOR 117.1
292 degrees 45.0 DME

Hays VOR 110.4
047 degrees 46.8 DME

Latitude N39 17.89
Longitude W098 27.96

*The Ringneck Ranch airstrip is 50 ft wide x 2600 ft long unimproved north/south sod runway with a 1200 ft gravel road over-run on the south end.

RINGNECK RANCH AIRSTRIP



Ringneck Ranch Airstrip
2 1/2 miles S S/E of Tipton

Runway Elevation 1500 ft MSL
with 800 ft terrain 1.5 east and 800 ft towers on high terrain east.

In the event of recent rain or snow,
please call for airstrip condition.
785-373-4835

Weather
Beloit, Kansas K61
AWOS 118.225
785-534-1141

I have seen this information on the Ringneck Ranch Airstrip.

Pilot: Please print your name legibly above

Pilot: Sign name on line above

Date: _____

Phone #: _____

Aircraft "N" number: _____

Fax this signed paper to 785-373-4059 **before**
utilizing the runway.

Image © 2009 DigitalGlobe
© 2009 Google

© 2009 Europa Technologies

39°17'59.49" N 98°27'30.01" W elev 1582 ft